Smith-Hill and Bedell, P.C.

PATENT AND TRADEMARK LAWYERS

12670 NW Barnes Rd., Suite 104 Portland, Oregon 97229 Telephone: (503) 574-3100

Telephone: (503) 574-3100 Facsimile: (503) 574-3197

John Smith-Hill

Daniel J. Bedell

RECEIVED CENTRAL FAX CENTER

FEB 0 8 2005

FACSIMILE COVER SHEET

To: Ian N. Moore

Art Unit 2661

Firm:

US PATENT AND

TRADEMARK OFFICE

Fax: 1-703-872 9306

Your ref: 09/847,079

From: Daniel J. Bedell

Date: February 8, 2005

Our ref: ZETT 2151

Pages: Cover + 13

BEST AVAILABLE COPY

SENT BY: SMITH-HILL AND BEDELL;

503 574 3197;

FEB-8-05 3:32PM;

Art Unit: 2661

Examiner:

Ian N. Moore

PAGE 3

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of

Toan D. TRAN et al

Application No: 09/847,079

Filed: May 1, 2001

For: BACK PRESSURE CONTROL SYSTEM FOR

NETWORK SWITCH PORT

REPLY TO THE OFFICE ACTION MAILED 10/18/2004

COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450

Sir:

Further examination and consideration of this application are requested in view of the following Amendments and Remarks.

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

□ BLACK BORDERS
□ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
□ FADED TEXT OR DRAWING
□ BLURRED OR ILLEGIBLE TEXT OR DRAWING
□ SKEWED/SLANTED IMAGES
□ COLOR OR BLACK AND WHITE PHOTOGRAPHS
□ GRAY SCALE DOCUMENTS
□ LINES OR MARKS ON ORIGINAL DOCUMENT
□ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER: _____

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.